



Installation



A photograph showing two different concrete finishes side-by-side. On the left is a smooth, dark grey concrete surface. On the right is a porous, light grey concrete surface with a rough, pebbled texture. A wooden plank is visible at the bottom, separating the two sections.


Regular

Porous





**Excellent Winter
Performance**



**Bldg Construction
Continued after
Installation**



Snow Piles on Pervious Areas





**After Snow
Piles Melted**





Cleaning

After Cleaning

